



PUNE MUNICIPAL CORPORATION

Date : 30/01/2026

Parvati Water Works Laboratory

Report ID : CH11

Report of Water Samples Collected as on 27/01/2026

Challan No : 12423000017 Challan Date : 27/01/2026 Amount (Rs.): 1620.00

पुणे महानगरपालिका
पार्वती जलकेंद्र पुणे ३०.

मालकाचे नाव : St. Arnold's Central School

जावक क्र. - CH-11
दिनांक ३०-१-२०२६

1) St. Arnold's Central School, SVD Campus, Near Suncity, Vadgaon Sheri, Pune - 14
Drinking Water Sample

As per I.S Standard No. 10500:2012				
Parameter	Results	Desirable Limit	Permissible Limit	Unit
PH	7.57	Between 6.5 To 8.5	No Relaxation	-
Turbidity	1.3	Max 1	Max 5	N.T.U
Total Hardness (as CaCO ₃)	53.0	Max 200	Max 600	PPM
Chlorides (as Cl)	16.0	Max 250	Max 1000	PPM
Alkanity (as calcium carbonate)	57.0	Max 200	Max 600	PPM
Nitrate Nitrogen (as NO ₃)	0.8	Max 45	No relaxation	PPM
Nitrite Nitrogen (as NO ₂)	0.04	-	-	PPM
Coliform	0	0	0	100ml
E-Coli	0	0	0	100ml
Residual Chlorine Test	1.6	0.2	-	PPM

Remark : सदरचा नमुना / नमुने मालकांनी स्वतः आणून दिला. उपरोक्त नमुना / नमुने हा प्रातिनिधिक असल्याचे गृहीत धरले आहे. सदरचा अहवाल हा वैयक्तिक माहितीसाठी असून, याचा वापर कुठल्याही प्रकारचा परवान्यासाठी केल्याने उद्भवणाऱ्या कायदेशीर बाबींस हे कार्यालय जबाबदार असणार नाही. तसेच नमुनांच्या उद्गमाविषयीचा पडताळा ह्या कार्यालयामार्फत केलेला नाही.

शेरा :

The Above Water Sample Is Potable as per IS:10500:2012

(Mandar Sardeshpande)

चेमिस्ट
Water Supply Department
पुणे महानगरपालिका
Pune Municipal Corporation